


Lift Station Condition Map

Summary of Impacted Parcels by Lift Station Service Areas

Service Area	Total Dwelling Units	Total Hotel Rooms	Total Number of Businesses
Dunham	119	82	1
Edgewater	208	0	11
Edgewater/Fairways	7	0	0
Edgewater/North Pier	14	0	3
Edgewater/Whitwam	101 (Under Construction)	92	1
Hawthorne	104	5	29
Hawthorne/Alco	96	0	0
Island Point	61	0	1
Vine St	173	0	2
Vine St/Lake St	28	0	0



St. Joseph SAW Grant Public Information Meeting No. 1



Sanitary Sewer Lift Stations

Condition Rating:

- Very Good
- Good
- Fair
- Poor
- Very Poor

Service Areas:

- Dunham
- Edgewater
- Edgewater/Fairways
- Edgewater/North Pier
- Edgewater/Whitwam
- Hawthorne
- Hawthorne/Alco
- Island Point
- Vine St
- Vine St/Lake St

April 22, 2017

0 1,000 2,000 Feet

