


Sanitary Sewer: Manhole Condition



St. Joseph SAW Grant

Sanitary Sewer Manhole Condition

- Condition: Good to Very Good
- Condition: Fair
- Condition: Poor to Very Poor
- Unknown Condition

City Limits

May 2017

